

Configuration overview for Pressure sensor SPAU
 SPAU-B2R-W-G18FD-L-PNLK-PNVBA-M12U
 #8001200

Basic configuration	
Feature	Value
Product type	SPAU Pressure sensor
Pressure measuring range	B2 -1 ... 1 bar
Pressure input	R Relative pressure
Type of mounting	W Wall mounting
Pneumatic connection	G18 G1/8
Thread type	F Female thread
Outlet direction	D Underneath
Display	L LCD, backlit
Electrical output 1	PNLK PNP or NPN or IO-Link
Electrical output 2	PNVBA PNP or NPN or 0 ... 10 V or 1 ... 5 V or 4 ... 20 mA
Electrical connection	M12 Plug M12, A-coded
Electrical outlet direction	U On top
Electrical accessories	Without accessories
Protective devices	Without
Certificate	Without